

Figure Contents

Figure 1 Illustration of Stevin's Ideal City	14
Figure 2 Map of Braga	17
Figure 3 Design method of Braga	18
Figure 4 Pedestrian walkway on core zone & Street Furniture with patterns representing Braga	19
Figure 5 Setbacks on a new Hotel.....	19
Figure 6 Links around the post office	20
Figure 7 Mapping of semarang old town	22
Figure 8 use of pavement in the streets of semarang	22
Figure 10 Districts and Road that define the city's image.....	27
Figure 11 Landmarks and Nodes that define the VOC Period Image.....	28
Figure 12 a map of Manado with reference to important buildings in 1920.....	29
Figure 13 Districts and Road Hierarchy that define the city's image in the Early East Indies period.....	31
Figure 14 Building height during the Early East Indies period	31
Figure 15 Landmarks and nodes defining the Early East Indies image.....	32
Figure 16 The Koppa Building in office district.....	33
Figure 17 the park replacing the exercise field node in the district	33
Figure 18 a map of Manado with reference to important buildings in 1945.....	34
Figure 19 road hierarchy and districts in the late period.....	35
Figure 20 Landmarks and nodes in the late period	36
Figure 21 Manado in the current period.....	37
Figure 22 Manado in the early east indies period	38
Figure 23 surviving building listed in dark red while lost building in light red ...	38
Figure 24 Current condition of church and monument.....	39
Figure 25 Old versions of the church.....	40
Figure 26 Minahasa Raad in the 1930's	41
Figure 27 Current condition of the Minahasa Raad.....	41
Figure 28 Park Condition in the 1930's.....	42

Figure 29 Current Condition of the Park	43
Figure 30 The old bank enclosed by the rennovation	44
Figure 31 Condition of the Javasche Bank in the 1930s.....	44
Figure 32 Ban Hin Kiong Temple in 1945.....	45
Figure 33 Ban Hin Kiong Temple in the current day	45
Figure 34 Current condition of the port	46
Figure 35 Jendral Sudirman street in the 1940's	47
Figure 36 Existing Section Diagram of Jendral Sudirman Street	48
Figure 37 Section Diagram of Dotulolong Lasut road from the start	49
Figure 38 Section Diagram of Dotulolong Lasut road in the end.....	49
Figure 39 Dotulolong Lasut Road in the 1940's	50
Figure 40 Existing Condition of Dotululung Lasut road	50
Figure 41 Sam Ratulangi Road in the past.....	51
Figure 42 current Javasche bank	55
Figure 43 Proposed Conservation method with link in red and the new building in blue.....	55
Figure 44 Diagram showing proposed conservation approach	56
Figure 45 Area of Conservation Design Guidelines	62
Figure 46 Evacuation Point Based on Government Regulation.....	63
Figure 47 Road Design for Wilhelmina Laan to Pier Boulevard.....	63
Figure 48 Road Design for Town centre, and church Piazza	64
Figure 49 Road Design for Main Chinatown Street	64
Figure 50 Road Design for Minor Chinatown Street	65
Figure 51 Typical Corner Shophouse facade in Chinatown	65
Figure 52 Shophouse Redesign based on old shophouse facade, left being new right old.....	66
Figure 53 Shophous Extension Massing in the future	66
Figure 54 Wilhelmina Laan Street Montage.....	67
Figure 55 Planting Schedule in Wilhelmina Laan	68
Figure 56 Chinatown Road Montage	69
Figure 57 Chinatown Streetscape Redesign.....	70

Figure 58 Town centre and church Piazza Montage.....	71
Figure 59 Reference Image for Town centre and Church Piazza	72
Figure 60 Planting Schedule for Town Centre Street Type	73
Figure 61 Redesign of Park.....	74
Figure 62 Park concept.....	76
Figure 63 Scaffolding system detail	76
Figure 64 Existing Javasche Bank	77
Figure 65 Link facade Design	78
Figure 66 Javasche Bank Groundfloor Plan	79
Figure 67 Existing building circulation and Functions	80
Figure 68 Void Building Analysis	81
Figure 69 Surviving Building	82
Figure 70 Surviving Facade Building	82
Figure 71 Redesign Zoning and Circulation	83
Figure 72 Groundfloor plan of interpretation centre.....	84
Figure 73 readapt old warehouse concept.....	84
Figure 75 Orthogonal Drawing of existing Minahasa raad.....	85
Figure 76 Plan of Readapted Minahasa Raad	87
Figure 77 Circulation of Adapted Minahasa Raad.....	87
Figure 78 Solid Void Analysis Diagram.....	88
Figure 79 Church Older Facade Interior	89
Figure 80 Comparison of older facade to existing façade.....	89
Figure 81 Existing Church Extension	90
Figure 82 Redesign Building Elevation	90
Figure 83 Redesign Building Groundfloor Plan	91